

# RAVNSBORG PHOTOS

***\*\*Highlighted Photos are not included due to the sensitive nature of these photos. Unredacted versions will only be presented to the Senate at the time of the Impeachment Trial in closed session.***

ORIGINAL LOCATION	FILE NAME	FOLDER	PHOTO DESCRIPTION (N, S, E, W refer to the direction of the camera)
ND #4	DJI_0023	TO BE PROVIDED	Boever in relation to large piece
	DJI_0024	TO BE PROVIDED	Boever & leg in relation to large piece
	DJI_0107	TO BE PROVIDED	Close-up of Boever w/ large piece
ND #5	437_0294	Initial collecton of evidence	W--approaching large piece
	437_0296	TO BE PROVIDED	N--Large piece, taken from crown of road
	437_0350	TO BE PROVIDED	W--large piece, Boever in background
	437_0351	Initial collecton of evidence	Close-up of large piece from above
	437_0357	TO BE PROVIDED	Boever taken from grass
	437_0358	TO BE PROVIDED	Boever taken from shoulder
	437_0360	TO BE PROVIDED	W--approaching Boever
	437_0361	TO BE PROVIDED	W--taken standing in ditch (shows slope)
	437_0378	TO BE PROVIDED	NE--taken from edge of lane of travel
	437_0396	Initial collecton of evidence	W--Gouge mark and large debris
	437_0398	Initial collecton of evidence	N--Misc. debris
	437_0411	Initial collecton of evidence	Close-up--larger piece of clear plastic
	437_0412	Initial collecton of evidence	NW--0411 in context
	437_0436	Initial collecton of evidence	W--Area of impact from edge of shoulder
	437_0437	Initial collecton of evidence	W--nut in lane of travel
	437_0439	Initial collecton of evidence	Close-up of 0437
	437_0470	Initial collecton of evidence	W--fuse/motor
	437_0487	Initial collecton of evidence	W--clear glass
	437_0489	Initial collecton of evidence	Close-up of 0489
	437_0492	Initial collecton of evidence	W--Flashlight location
437_0493	Initial collecton of evidence	Close-up of flashlight and debris	
437_0494	Initial collecton of evidence	Close-up of flashlight	

	437_0511	Initial collecton of evidence	Close-up of large piece of clear plastic
	437_0514	Initial collecton of evidence	Close-up--larger piece of clear plastic
	437_0546	Initial collecton of evidence	W--Gouge mark and large debris
	437_0547	Initial collecton of evidence	Close-up--Gouge mark
	437_0550	Initial collecton of evidence	Close-up--Bone scrape
	437_0573	TO BE PROVIDED	E--Boever taken from shoulder
	437_0637	Initial collecton of evidence	Close-up--Flashlight taken from shoulder
	437_0638	Initial collecton of evidence	Close-up--Flashlight showing lens
	437_0639	Initial collecton of evidence	Zoomed-in on flashlight
	437_0640	Initial collecton of evidence	Zoomed-in on flashlight lens
	437_0644	Initial collecton of evidence	Flashlight being collected, lit
Property-Evidence	IMG_0249	Walking Scene	W--from edge of scene
	IMG_0259	Walking Scene	W--from well east of passing sign
	IMG_0268	Walking Scene	W--from just east of passing sign
	IMG_0276	Walking Scene	W--Approaching area of impact
	IMG_0285	Walking Scene	W--Area of impact from lane of travel
	IMG_0294	Walking Scene	W--approaching larger piece of clear plastic
	IMG_0299	Walking Scene	W--approaching gouge and bone scrape
	IMG_0300	Walking Scene	W--approaching large debris
	IMG_0301	Walking Scene	W--almost even with gouge and bone scrape
	IMG_0303	Vehicle Debris	W--approaching large debris
	IMG_0308	TO BE PROVIDED	W--large piece, Boever in background
	IMG_0309	TO BE PROVIDED	W--Large debris, Boever taken from shoulder
	IMG_0311	TO BE PROVIDED	W--Boever taken from shoulder
	IMG_0313	TO BE PROVIDED	NW--Boever taken from shoulder
	IMG_0314	TO BE PROVIDED	NW--Boever taken from shoulder
	IMG_0315	TO BE PROVIDED	N--Boever taken from shoulder
	IMG_0318	TO BE PROVIDED	E--Boever taken from shoulder
	IMG_0319	TO BE PROVIDED	E--Boever taken from edge of shoulder
	IMG_0321	TO BE PROVIDED	E--Boever taken from middle of shoulder
	IMG_0325	TO BE PROVIDED	E--Approaching deceased

Property-Evidence	IMG_0327	Walking Scene	E--large debris
	IMG_0332	Secondary collecton of evidence	E--approaching gouge and bone scrape
	IMG_0334	Secondary collecton of evidence	E--showing gouge with area of impact in distance
	IMG_0338	Secondary collecton of evidence	E--approaching area of impact
	IMG_0341	Secondary collecton of evidence	E--taken from even with large plastic
	IMG_0345	Secondary collecton of evidence	E--nearing area of impact
	IMG_0349	Secondary collecton of evidence	E--nearing area of impact, fuse/motor visible
	IMG_0393	Vehicle Debris	E--from area of impact to edge of crime scene
	IMG_0423	Vehicle Debris	W--fuse/motor, windshield glass
	IMG_0424	Vehicle Debris	Close-up--windshield glass
	IMG_0425	Vehicle Debris	Close-up--windshield glass
	IMG_0426	Vehicle Debris	Close-up--windshield glass
	IMG_0427	Vehicle Debris	Close-up--fuse/motor
	IMG_0461	Vehicle Debris	Close-up--flashlight
	IMG_0494	AG Vehicle on Scene	AG vehicle--head-on
	IMG_0495	AG Vehicle on Scene	AG vehicle--driver's side
	IMG_0522	AG Vehicle on Scene	AG vehicle--passenger side
	IMG_0569	AG Vehicle on Scene	AG vehicle--from rear
	IMG_0983	Walking Scene	Grass in Ditch
	ND #9	445_0003	AG Vehicle in Shop
445_0032		AG Vehicle in Shop	AG vehicle--damage to windshield
445_0033		AG Vehicle in Shop	AG vehicle--damage to windshield
445_0034		AG Vehicle in Shop	AG vehicle--damage to side mirror
445_0036		AG Vehicle in Shop	AG vehicle--windshield close-up
445_0055		AG Vehicle in Shop	AG vehicle--damage to pillar
445_0062		AG Vehicle in Shop	AG vehicle--paint scrapes
445_0068		AG Vehicle in Shop	AG vehicle--Victim impact
445_0198		AG Vehicle in Shop	AG vehicle--front interior from driver's seat
445_0204		AG Vehicle in Shop	AG vehicle--rear interior, glasses
445_0209		AG Vehicle in Shop	AG vehicle--papers and glasses in rear sear
445_0210		AG Vehicle in Shop	Close-up of 0209

	445_0211	AG Vehicle in Shop	AG vehicle--front interior from passenger door
	445_0212	AG Vehicle in Shop	AG vehicle--Glass lenses
	445_0213	AG Vehicle in Shop	AG Vehicle - interior
	445_0214	AG Vehicle in Shop	AG Vehicle - interior
	445_0215	AG Vehicle in Shop	AG Vehicle - interior
	445_0221	AG Vehicle in Shop	AG vehicle--rear interior from passenger side
	445_0223	AG Vehicle in Shop	AG Vehicle - interior
	445_0224	AG Vehicle in Shop	AG vehicle--glove box and passenger area
ND #45	IMG_3124-IMG_0023 - enhanced compare-export1-12-0	Recreation Photos	Original
	IMG_3124-IMG_0023 - enhanced compare-export24-34-0	Recreation Photos	LE Photo
	IMG_3124-IMG_0023 - enhanced compare-export35-35-0	Recreation Photos	Method
	IMG_3124-IMG_0023 - enhanced compare-export35-44-0	Recreation Photos	Method
	IMG_3124-IMG_0023 - enhanced compare-export35-50-0	Recreation Photos	Final